

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 20 T 50N R 34W	3
	S 20 T 50N R 34W	1
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/30/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 20) North 1/16 corner between Sections 19 and 20. Not previously monumented.

(1-Sec. 20) West 1/16 corner between Sections 17 and 20. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 20) Established the position for the corner midway and on the Section line between Section  
corner 1314.80' north and Quarter corner 1314.80' south.

(1-Sec. 20) Established the position for the corner midway and on the Section line between Section  
corner 1315.48' west and Quarter corner 1315.48' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
5" W.Birch N01°W 19.95' mrkd "1/16S BT"  
5" Maple N88°E 46.5' do  
4" Oak S36°E 42.2' do  
5" Oak S81°W 41.4' do  
Set sq'd cedar post adjacent.  
E= 7878083.121 N= 216362.639

(1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
3" Oak N40°E 7.55' mrkd "1/16S BT"  
9" R.Pine S60°E 33.85' do  
6" Oak in clump S81°W 14.4' do  
9" W.Pine N36°W 17.45' do  
Set Sq'd cedar post adjacent.  
E= 7878495.365 N= 216755.791

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID DI1837: N= 221257.624 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/02/2013

For the Michigan Department of Natural Resources, Forest Resources Division

