

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 11 T 50N R 34W	7
	S T R	(GCDB 600560)
	S 11 T 50N R 34W	6
3. Miscellaneous Property in Sec.	S T R	(GCDB 560560)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 7 12/14/15  
6 12/14/15 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(7-Sec. 11) North 1/16 corner between Sections 11 and 12.  
Not previously monumented.

(6-Sec. 11) Northeast 1/16 corner, Section 11.  
Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(7-Sec. 11) Established the position for the corner midway and on the Section line between Section  
corner 1325.63' north and the position for the Quarter corner K4, not monumented, 1325.63' south.

(6-Sec. 11) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners, those to the east and north being monumented.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
14" Cedar N83°E 6.55' mrkd "1/16S BT"  
12" Cedar S01°E 21.25' do  
5" Cedar S55°W 8.5' do  
12" Cedar N66°W 16.7' do  
Set sq'd cedar post adjacent.  
E= 7884549.993 N= 219445.532

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
9" Maple N27°E 28.3' mrkd "1/16S BT"  
13" Poplar S52°E 25.9' do  
7" Maple S01°W 22.7' do  
13" Hemlock S83°W 33.05' do  
Set sq'd cedar post adjacent.  
E= 7884148.719 N= 219451.674

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID D08499: N= 221257.621 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski Date 01/21/2016  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

