LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #	
(County)	_		
1. Public Land Survey	TR TR		
2. Property Controlling in Section	S 18 T 51N R 31W S 18 T 51N R 31W S T R	PCC N. of #8 B6	
3. Miscellaneous Property in Sec.	S T R R		Degister of Deeds Chara & Eth North
4. Lot No. Re	ecorded Plat		Register of Deeds Stamp & File Number
5. Private Claims			A B C D E F G R I J)
i, Stephan J. Szyszkoski ,	in a field survey on 01	/09/2012 do hereby state	3

above were in conformance with regulations and rules therefore as required in the current manual of survey 5 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(PCC N. of #8) A property controlling corner on the West 1/16 line of Section 18, being the line between Government Lots 4 & 5, between Skanee Road and the Silver River. Not previously monumented.

(B6) Center of Section 18. 1970 - Established and monumented by A.O.Enger RLS. Set 1"IDx36" iron pipe with 4" aluminum cap. Red Maple 5" S08E 38.8', Red Maple 3" N53E 44.2'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(PCC N. of #8) Established the corner on the West 1/16 line, on a straight line between 1/16 corner #8 143.04' south and a Special Meander Corner on the south shore of the Silver River, also set this date, 533.88' north. The position monumented lies approx. 55' north of the constructed centerline of the Skanee Road. This position does NOT fall on the northerly Right-of-Way line of Skanee Road. attempt was made to reestablish the location of the Right-of-Way of Skanee Road (abandoned State Hwy. M-35).

(B6) The 1970 monument was recovered in good condition and measurements to adjacent corners confirm that the monument occupies the 1970 position. The 1970 witnesses were not recovered. The corner position falls within a 5-10 year old clear cut and the 1970 witnesses have apparently been cut down. No evidence remains above the snow. I accept the monument as a careful and faithful establishment of the position of the corner. 1/16 corner #8 was found 1329.10' west and Quarter corner C6 was found 2648.60' east. The angle formed by these, measured clockwise from the west, was found to be 180 deg. 00' 31".

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(PCC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. (B6) Fd. 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: mrkd "POL BT" 6" B.Ash N42E 17.0' 2" Sugar S10W 15.7' mrkd " X X " 6" B.Ash S73E 7.15 8" Maple S34W 13.3 B.Ash S73E 7.15' 3" W.Spruce N20E 15.2' do "C1/4 BT' do 2" W.Spruce N88W 4.85' do Cedar N88W 23.4' 3" W.Spruce N50W 38.2' do Set sq'd cedar post adjacent. Set sq'd Cedar post adjacent. Bearings are magnetic. Bearings are magnetic.

Signed by Surveyor's Michigan License No.

Date

01/24/2012

33986

For the Michigan Department of Natural Resources, Forest Management Division

16807 16808 FORM APPROVED BY MICHIGAN STATE BOARD

14, 1975 evised Jan., 1983 Rervised Oct., 1995

STEPHAN .

YSZKOSK

LAND

SURVEYOR

CAND SO

18