

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| | | |
|---------------------------------------|---------------------------------------|---------------|
| Baraga <small>(County)</small> | Located In: | Corner Code # |
| 1. Public Land Survey | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S <u>26</u> T <u>51N</u> R <u>32W</u> | <u>3</u> |
| | S <u>26</u> T <u>51N</u> R <u>32W</u> | <u>4</u> |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 4. Lot No. _____, Recorded Plat _____ | | |
| 5. Private Claims | | |

Register of Deeds Stamp & File Number

| | | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 10 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

I, Stephan J. Szyszkoski, in a field survey on 3 08/10/2011 do hereby state
4 08/18/2011
 that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
 above were in conformance with regulations and rules therefore as required in the current manual of survey
 Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
 re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
 on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 26) North 1/16 corner between Sections 26 and 27. Not established in the original survey.

(4-Sec. 26) Northwest 1/16 corner, Section 26. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 26) Established the corner midway and on the Section line between Quarter corner 1324.62'
 south and Section corner 1324.62' north. The position for the corner falls in or adjacent to the
 Silver River and cannot be monumented. Established a Witness Corner on the Section line 49.55' north
 of the corner position.

(4-Sec. 26) Established the corner at the intersection of straight lines connecting opposite 1/16
 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
 49.55' north of the position for the corner and
 on the Section line between I9 and I10.
 Set measuring nail with MDNR tag in the side of:
 5" W.Pine N02E 24.2' mrkd "WC BT"
 6" Maple N34E 19.65' do
 4" Maple S68E 10.2' do
 8" W.Pine S87W 4.45' do
 Set sq'd Cedar post adjacent.
 Bearings are magnetic.

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
 Set measuring nail with MDNR tag in the side of:
 5" Balsam N08E 20.95' mrkd "1/16S BT"
 7" Spruce S87E 23.3' do
 6" Y.Birch N81W 11.95' do
 4" twin Y.Birch N30W 26.9' do
 Set sq'd Cedar post adjacent.
 Bearings are magnetic.

Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 08/30/2011

For the Michigan Department of Natural Resources, Forest Management Division



16718
 16719