

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski
For corner(s) in: Baraga County

Field Survey Date: 05/17/2016

Original Public Land Survey Corner				Corner Code
S	<u>5,6,7,8</u>	T	<u>52N R 33W</u>	<u>C3 (GCDB 200600)</u>
S	<u> </u>	T	<u> </u>	<u> </u>
S	<u> </u>	T	<u> </u>	<u> </u>
S	<u> </u>	T	<u> </u>	<u> </u>
Protracted Public Land Survey Corner				Corner Code
S	<u> </u>	T	<u> </u>	<u> </u>
S	<u> </u>	T	<u> </u>	<u> </u>
S	<u> </u>	T	<u> </u>	<u> </u>
S	<u> </u>	T	<u> </u>	<u> </u>

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3			●											3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

Section corner common to Sections 5-6-7-8. 1999 - Remonumented by Michael Mileski PS 39091 for Baraga County Remonumentation. He found a 1/2"x12" iron rod inside a 1"x24" iron pipe badly bent, the base of which appeared to be in the original position. Mr. Mileski accepted the pipe as the best available evidence of the position of the original corner and set a 1"IDx36" galvanized iron pipe and cap 12" below the road surface. Set 7" spike in: 7" Aspen N69°E 81.18'; 8" Balsam N50°W 41.28'; 16" Balsam N01°W 34.26'; Set 6' Steel fence post with sign South 27.0'. Recorded in Liber 5 of LC Page 101 and 102.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

The 1999 county monument was not recovered. Found the bent 1"x24" iron pipe, still in place, base appearing plumb, at record bearing and distance from the 1999 NBT witnesses of record. The 1999 NBTs marked by Mr. Mileski are now all cut stumps, only the Balsam N01W 34.26' still exhibiting the measuring nail set in 1999. A distance measured to C2 was found to be 2632.68' compared to Mr. Mileski's 1999 measurement of 2632.82'. A distance measured to D3 was found to be 2636.25' compared to Mr. Mileski's 1999 measurement of 2636.38'. I accepted the position of the base of the pipe, corroborated by the 1999 witnesses, as the best available evidence of the 1999 position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

At the position of the base of the found, bent 1" ID iron pipe, I set a 5/8"x30" rebar capped with a yellow plastic MDNR cap PS33986, set 6" below the gravel surface. Set measuring nail with MDNR tag in the side of:

3" Spruce N17°E 31.45'	mrkd "S5 NBT"
6" Ash S25°E 43.3'	"S8 NBT"
5" Ash S28°W 44.5'	"S7 NBT"
8" Maple N40°W 39.0'	"S6 NBT"

The 1999 sign post with sign is South 27.3'

Bearings are magnetic.

Stephan J. Szyszkoski

05/25/2016



Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908