SURVEY & REMONUMENTATION

FEB 2 3 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECT	TION	mig izedaniement of M	st 14, misti. F.	A. 1970
Baraga	Located	I In: Corner C	ode#	RECEIVED FOR RECORD THIS 318
1. Public Land Surve	T T T	Rthe south	h MC for nernmost of the River	DAY OF DECEMBER A.D. 1997 A 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGE 819
2. Property Controlling in Section	ng S T S T		A-11 and	Telda Biskop
3. Miscellaneous	S T		·	BARAGA COUNTY REGISTER OF DEEDS
Property in Sec.	S T	R		Register of Deeds Stamp & File Number
4. Lot No ,	Recorded Plat			
5. Private Claims				A B C D E F G H I J K L M 2 - 6 - 5 - 4 - 3 - 2 - 1
that under requirements o above were in conformar survey instructions of the decree of a Court of Law conformance with the rule	f P.A. 74, Michigan P.A. of uce with regulations and rul United States Department of and for that the corner po	on 8 December, 19 1970, the corner points ment es therefore as required in t of the Interior, Bureau of Land ints mentioned in lines 3, 4 Land Surveyors or by a Dece- ound as expressed below:	tioned in lines 1 at he current manual Management or l and 5 above wer	nd 2 4 7 8 9 10 11 12 12 15 16 16 16 17 17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				8 - 19 - 2021222324
A. Description of original monument and accessories and/or subsequent restoration:				10 30 29 28 27 26 25
MC #4; North Mean the Sturged	nder Corner for the s on River between A-	southernmost crossin 11and A-12, T52N, I	g of R33W;	12 31 32 33 34 35 36
Originally estab D.S. in 1845 a	olished during U.S. S nd monumented wit	Survey conducted by h a wood post witne	William Burt, ssed by a	APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County
	12 N57°I		-	16.9-97
No subsequent	record evidence bea	aring upon the location	on of this cor	ner was found
		or method applied in resto		•
MC #4; North Mear		southernmost crossin		
corner of section approximately (on 31 and the NW co 60 feet south of the	orner of section 31.	This corner putthe river. A	portionate distance between the W¼ position falls in the Sturgeon River witness corner was established on the meander corner.
. Description of mon	ument for corner and acc	cessories established to p	erpetuate locati	ng the position of the corner:
AC #4; North Mear A-11 and A	nder Corner for the s A-12, T52N, R33W;	outhernmost crossin	g of the Stur	geon River between
Set a 1"(I.D.) x 4" below the gr	36" galvanized iron round.	pipe with cap stamp	ed as to loca	ation
Set 7" spike	W/side	15" Apple	N05°E	133.32'
Set 7" spike		15" Twin Box Elder		59.97' ZILLE BE MICHIGAL
Set 7" spike Set 7" spike	NW/side S/side	9" Box Elder 12" Elm	N61°E S70°E	95.08' MICHAEL **
occi shive		post w/ yellow sign		96.67' MILESKI PROFESSIONAL SURVEYOR
		except the apple tree		with upper No. No.

Signed by Date 23 Oec 1997
Surveyor's Michigan License No. 39091

LIBER 4 PAGE 819

around the tree at the upper blaze were painted red.