

SURVEY &
REMONUMENTATION

FEB 23 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga

(County)

Located in:

Corner Code #

1. Public Land Survey

T 52N R 33W

#111 West MC

T R

between B-1 and

T R

C-1

T R

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Michael Mileski, in a field survey on 6 December, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC #11; West Meander Corner between B-1 and C-1, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Maple 12 N18°W 15 lks.

No subsequent record evidence bearing upon the location of this corner was found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC #11; West Meander Corner between B-1 and C-1, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the N¼ corner of section 6 and the NE corner of section 6. This corner position falls on the old river bank approximately 22 feet west of the left (west) bank of the Sturgeon River as presently located.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #11; West Meander Corner between B-1 and C-1, T52N, R33W;

Set a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location flush with the ground.

Set 7" spike	SE/side	10" Balsam	S37°W	37.70'
Set 7" spike	N/side	8" Sugar Maple	S81°W	48.05'
Set 7" spike	N/side	17" Yellow Birch	N52°W	38.40'
Set 7" spike	NE/side	8" Sugar Maple	N26°W	65.13'
		6' Steel fence post w/ yellow sign	East	1.5'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

RECEIVED FOR RECORD THIS 31ST
DAY OF DECEMBER A.D. 1997 AT
10:30 A.M. AND RECORDED IN
LIBER 4 OF LAND CORNER
RECORDATION RECORDS ON PAGE
826.

Relda Bishop

BARAGA COUNTY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

APPROVED LAND CORNER
P.A. 345 OF 1990
Baraga County

16-9p-97
MAI



LIBER 4 PAGE 826

Signed by *Michael Mileski*
Surveyor's Michigan License No. 39091

Date 23 Dec 1997