

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION

Baraga
 (County)

Located In:

Corner Code #

- 1. Public Land Survey T 52N R 33W
- T _____ R _____
- T _____ R _____
- T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
- in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
- Property in Sec. S _____ T _____ R _____

#15 West MC for
 the easternmost
 crossing of the
 Sturgeon River
 between A-11 and
 B-11

RECEIVED FOR RECORD THIS 14TH DAY OF
 JANUARY A. D. 1999 AT 10:30 A. M.
 AND RECORDED IN LIBER 5 OF LAND
 CORNER RECORDATION RECORDS ON PAGE
 37.

Relda Bishop
 BARAGA COUNTY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Michael Mileski, in a field survey on November, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC #15; West Meander Corner for the easternmost crossing of the Sturgeon River between A-11 and B-11, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented with an ash post witnessed by a White Ash 6 N74°W 20 lks. and a White Ash 6 S41°W 19 lks. This corner is not indicated in the field notes of a survey of the north line of section 31 conducted by persons unknown for Andrew and Joseph Lescelius on 5 September 1933.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC #15; West Meander Corner for the easternmost crossing of the Sturgeon River between A-11 and B-11, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the NW corner of section 31 and the N¼ corner of section 31. This corner position falls approximately 110 feet west of the right (west) bank of the river. A witness corner was established on the section line at a distance of 90.00 feet easterly of the proportioned meander corner. The witness corner is located approximately 20 feet west of the water's edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #15; West Meander Corner for the easternmost crossing of the Sturgeon River between A-11 and B-11, T52N, R33W;

The witness corner described in Part B was monumented with a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location flush with the ground.

Set 7" spike	SW/side	6" Elm	S47°E	12.62'
Set 7" spike	E/side	23" Black Ash	N44°W	69.61'
		7' Steel fence post w/ yellow sign	West	1.5'

Both trees were marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

APPROVED LAND CORNER
 A 345 OF 1990
 Baraga County



Signed by _____
 Surveyor's Michigan License No. 39091

Date 28 Dec 1998