LAND CORNER RECORDATION CERTIFICATE

and the state of the	Filing Requirement of Act 74, Mich. P.A. 1970				
Baraga (County) 1. Public Land Survey	Located In: T_52N R_33W T R T R	#16 East MC for the easternmost crossing of the	RECEIVED FOR RECORD THIS 14TH DAY JANUARY A. D. 1999 AT 10:30 A. M. AND RECORDED IN LIBER 5 OF LAND CORNER RECORDATION RECORDS ON PAGE 36. **Color Bushop**		
_	TR STR STR STR	Sturgeon River between A-11 and B-11	BARAGA COUNTY REGISTER OF DEEDS Register of Deeds Stamp & File Number		
4. Lot No, Records. Private Claims	rded Plat		A B C D E F G H I J K L M 1		
that under requirements of P.A. 74 above were in conformance with survey instructions of the United S	 Michigan P.A. of 1970, the coregulations and rules therefore States Department of the Interior that the corner points mention Michigan Board of Land Survey 	vember , 19 98 do hereby sta orner points mentioned in lines 1 and as required in the current manual r, Bureau of Land Management or by sed in lines 3, 4 and 5 above were ors or by a Decree of a Court of Langessed below:	12 4 7 8 9 10 11 12 of ; in 6 10 17 15 14 13		
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.					
A. Description of original mor	nument and accessories and	or subsequent restoration:	11:		
MC #16; East Meander C the Sturgeon Ri	Corner for the easternm ver between A-11and I		12 31 32 33 34 35 36-		
D.S. in 1849 and m Tamarack 10 S8 This corner is not in	nonumented with a sug 37°E 10 lks. and a ndicated in the field not ted by persons unknow	conducted by William Burt far maple post witnessed I Fir 6 N56°E 11 lks. tes of a survey of the nort in for Andrew and Joseph	by a APPROVED LANCE NER PA. 345 OF LINER Baraga Co. 19		
B. Description of corner evid	dence found and/or method	applied in restoring or reestablis	shing corner:		
MC #16: East Mounday	Saraar far tha anataram	ant areasing of the Ctures	on Diver between		

East Meander Corner for the easternmost crossing of the Sturgeon River between A-11 and B-11, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the NW corner of section 31 and the N¼ corner of section 31. This corner position falls in the Sturgeon River. A witness corner was established on the section line at a distance of 107.00 feet east of the proportioned meander corner. The witness corner is located approximately 18 feet east of the water's edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #16; East Meander Corner for the easternmost crossing of the Sturgeon River between A-11 and B-11, T52N, R33W;

The witness corner described in Part B was monumented with a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location flush with the ground.

Set 7" spike	SW/side	8" Elm	S38°E	12.66'
Set 7" spike	NE/side	Power Pole	S51°E	45.42'
Set 7" spike	S/side	9" Twin Apple	N72°E	61.65'
	7' Steel fend	ce post w/ yellow sign	North	1.5'

The apple tree was not blazed. The power pole was marked with a vertical red paint stripe. The elm tree was marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

Signed by Surveyor's Michigan License No._ <u> 39091</u>

MILESKI **PROFESSIONA** SURVEYOR