SUHVEY & TEMONUMENTATION

APR 0 8 1996

expressed below:

on this certificate.

COMMISSION.

BARRY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

DEC 15 2 08 PM '95

For corners in		•	Sandry Schondelmarger
BARRY	Located In:	Corner Code ##	REGISTER OF DEEDS
PRAIRIEVIC LEAD WHITE PRAIRIEVIC LEAD WHITE PARTY REFERENCE MONUMENT TO MEANDER POST ON BASE LINE AT WEST SHORE OF LITTLE LONG LAKE	T R T R T R E T R		002359
3. Miscellaneous S	T TN R 10W T R R		Register of Deeds Stamp & File Number
4. Lot No, Record 5. Private Claims, in a do hereby certify that under requirem in lines 1 and 2 above were in conficurrent manual of survey instruction Management or by a decree of a Coulabove were in conformance with the Court of Law; established, re-esta	a field survey onOC nents of P.A. 74 Michigan P.A formance with regulations a is of the United States Depa in of Law and/or that the corn rules of the Michigan Board	TOBER 24 , 19 95 A. of 1970, the corner points mentioned rules therefore as required in artment of the Interior. Bureau of the points mentioned in lines 3, 4 at of Land Surveyors or by a Decree	2 6 5 4 3 2 1 3 5 10 10 11 12 12 13 14 13 14 13 14 13 15 14 13 16 15 14 13 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

- MEANDER CORNER ON WEST SIDE OF LITTLE LONG LAKE WAS ESTABLISHED BY GENERAL LAND OFFICE DEPUTY SURVEYOR JOHN MULLETT IN DECEMBER, 1825. THE NOTES INDICATE THAT THE CORNER WAS 37.16 CHAINS EAST OF J-13, THE NEAREST STANDARD CORNER NOT IN A LAKE. MEANDER POST NOTED AS "LEAVE ELM 8 S22 1/2W 40." LAKE SET POST ASPEN 10 S24E 29
- 2. RESURVEY OF PRAIRIEVILLE TOWNSHIP BY BARRY COUNTY DEPUTY SURVEYOR JOHN Q. CRESSY IN OCTOBER, 1884, NOTES INDICATE THAT FROM J-13 TO THE WEST BANK OF LITTLE LONG LAKE IS 30.12 CHAINS. CRESSY'S NOTES INDICATE THAT THE SOUTHWEST CORNER OF SECTION 36 IS "IN LAKE." CRESSY DID NOT SET A POST ON THE SHORE, AND NO WITNESS WERE NOTED.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NO DIRECT EVIDENCE REMAINS OF THE GENERAL LAND OFFICE SURVEY OR THE CRESSY RESURVEY BETWEEN J-13 AND LITTLE LONG LAKE. THERE ARE SEVERAL HUNDRED FEET OF MARSH BETWEEN THE OPEN WATERS OF LITTLE LONG LAKE AND THE HIGH GROUND TO THE WEST; THIS WOULD ACCOUNT FOR THE DIFFERENCE IN DISTANCE CITED BY CRESSY AND MULLETT. AFTER RESTORING THE BASE LINE BETWEEN LITTLE LONG LAKE AND GULL LAKE, AND TRAVERSING TO J-13 T1N R10W AND J-1 T1S R10W, DETERMINED THAT BEST METHOD OF RESTORATION OF MEANDER CORNER WOULD BE TO PLACE IT ON LINE BETWEEN RESTORED POINT ON BASE LINE ON EAST SIDE OF LONG LAKE AND J-13, AS CLOSE AS IS PRACTICAL TO THE OPEN WATERS OF LITTLE LONG LAKE. SET HARRISON MONUMENT ON SMALL HIGH SPOT NEAR OPEN WATER. TWO PARALLEL EAST-WEST FENCES INTERSECT THE LAKE; THE OLDER FENCE IS 8' NORTH OF THE MONUMENT, THE NEWER FENCE IS 14.5'
NORTH OF THE MONUMENT NORTH OF THE MONUMENT.

SEE REVERSE OF THIS FORM FOR GRAPHICAL REPRESENTATION

APPROVED BY PEER REVIEW AT A MEETING HELD ON

C. Description of monument for corner and accessories established to perpetuate : BEIAN GENEROLDS tion of the cordeUNTY SURVEYOR

SET STANDARD KALAMAZOO COUNTY REMONUMENTATION MONUMENT (HARRISON) WITNESSES:

13.67 NAIL AND TAG IN N SIDE OF 5" ELM N82°E NAIL AND TAG IN S SIDE OF 8" ELM S66°E 12.27 15.00 NAIL AND TAG IN E SIDE OF 10" ELM S24°E S25°W 29.53" NAIL AND TAG IN SE SIDE OF 12" ELM **EAST** 19.5'+/-EAST SHORE OF LITTLE LONG LAKE 15.5'+/-NORTH EAST SHORE OF LITTLE LONG LAKE

31602

BRIAN REYNOLDS LAND SURVEYOR NO. 31602 IANDSU

Signed by

Date

A) (7) (1) (1)

