

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. 25 N. 13 W.		B-1; C-1
2. PROPERTY CONTROLL- 6 T. 25 N. 13 W. ING IN SECTION_____		1
3. MISCELLANEOUS PROPERTY IN SECTION_____ T. N. S. R. E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 13, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XX
C: Continued;

1
Fd 1/2" Rod w/RLS Cap (Buried)(#13030)
5" W.Pine S33°E 53.15
4" W.Pine S40°W 54.20
Set Ced. Post w/loc tag S. 33'
Ctr. E-W Gravel Rd. N. 1'±
Fd. Well Pt. S87°40'E 258.50

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- C-1 Re-established Cor. to 5&6 1.63 chains E. of Cor. to 31 & 32 on S. line of T26N-R13W per 1839 G.L.O. survey and also per Pettitt sur. of 1900±, Liber "0", Pg.6 of old Co. Sur. records. Fn line south is east 19'±.
- B-1 Accepted Fd. 3" pipe for N 1/4 Cor. of Sec.6. Cor also used by RLS, G. DeLaMater in 1978 certificate survey of Sec.6. Corner fits 1900± survey of Sec.6 by Co Surveyor J.A. Pettitt; large brown Co. Surveyor Record Liber "0", Pg.6
- 1 Fd NE Corner of Fr1. NW 1/4 of Fr1. NW 1/4 of S-6 as set by RLS, G. DeLaMater in 1978 certificate survey. Cor. is on line between the NW Cor. of Sec.6 (25-13) and the S 1/4 Cor. of Sec.31 (26-13) & at prorated distance to GLO sur. between the N 1/4 Cor & NW Cor. of Sec.6.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1
Set 5/8"x36" Re-Rod w/R.L.S Cap
15" Maple S38°E 38.7
16" Maple S37°W 44.6
Ctr. E-W Gravel Rd. S. 4'±
Sec. Cor to 31&32
T26N-R13W N89°36'W 107.58'
Set Ced. Post w/loc Tag S. 33'

B-1
Fd 3" pipe
9" Maple S15°E 18.41
18" Maple S41°W 22.88
Set Ced. Post w/loc tag S 33'
Ctr. E-W Gravel Rd N 5'
T26N-R13W
S 1/4 Cor S-31; N88°10'W 35.94

SIGNED BY Carl F. Roser 3-31-81 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Colfax Township
BENZIE COUNTY