## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Benzie (County)			Located	i In	Corner Code #										
1. Public Land Survey		T T		- R											
Property Controlling in Section	S 31 S 31	T	25N 25N	R 13W	11 12										
Miscellaneous     Property in Section	\$ \$	- ' Т - Т	2514	R R				Registe	r of De	eds S	tamp	& Fil	le Nı	ımbe	ər
4. Lot No:	Recorde	ed Pla	at:		- A	В	СБ	E F	G	нι	J	к	L	м	
5. Private Claims: _						- 2	-6-	5 -	-4		3	_2-	Ī	1	
I, <u>Craiq W. McVean</u> , in a frequirements of PA 74, Mi and 2 above were in conforthe current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board of established, re-established	chigan PA rmance wit vey instruct nagement lines 3, 4 a f Land Su	of 197 th regi ctions or by and 5 irveyor	70, the outline to of the to decree above we say the total contract of the total contrac	corner points and rules the Jnited States of a Court of ere in confor a Decree	mentioned in lines 1 perfore as required in a Department of the flaw and/or that the mance with the rules of a Court of Law;	3 - 4 - 5 - 6 - 7 -	7 18 19	8 _	9 16		15	—11- —14- —23-	+	_12	

A. Description of original monument and accessories and/or subsequent restoration:

- 11 1890 "Plat of Beecher" L. 1 of plats, P. 48 L. H. Cannon. Cedar stake 2 1/2" square x 2' long
  - 1893 "Plat of Scovelle's Add. To Beecher" L. 1 of plats,

NOTE: Not more than 2 corners, all in the same town and range, may

- p. 61 D. F. Holden Cedar post 2" square and 30" in length. 1974 Rec. Survey L. 1, p. 374 L. J. Czubak 5/8" R. rod with cap set.
- 1) 8" Apple N75°W 80.03'; 2) 8" Apple S80°W 49.36';
- 3) 8" Apple S60°W 19.38'

be recorded on this certificate.

- 12 1893 "Plat of Scovelle's Add. to Beecher" L. 1 of plats,
  - p. 61 D. F. Holden Cedar post 2" square and 30" in length.
  - 1974 Rec. Survey L. 1, p. 374 L. J. Czubak 5/8" R. Rod with cap set.
  - 1) 12" Poplar N80°W 39.25'; 2) Tw. 10" Elm N70°W 5.75';
  - 3) 6" Poplar N20°E 19.26'
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 11 SW 1/16 Corner Sec. 31 Fd. Bent 5/8" x 24" rebar per Czubak. No evidence of record cedar post. Bent 5/8" rebar fits witness #1 & 3. #2 is gone. Iron fits plats dimension within reason. Bent 5/8" rebar accepted as the best available evidence of the position of the corner.
- 12 CS 1/16 Corner Sec. 31 Fd. capped 5/8" rebar per Czubak. No evidence of cedar post. Corner in wet grassy marsh. 5/8" CIR fits stump of witness #3. #1 & 2 are gone. 5/8" CIR accepted as the best available evidence of the position of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 11 Replaced bent 5/8" x 24" rebar with stamped 2" Alum. Cap on 5/8" x 34" rebar - Down 0.4'. Set Blue Carsonite Post with loc. tag 1' SE. East 59.95' (60' - P) to Fd. 1/2" CIR #35591

N74°W 79.96' to Fd. nail in S. side 18" Apple (#1) S15°E 95.59' to set N & T in E. side 16" Cherry S56°E 34.73' to set N & T in SW side Tw. 6" & 4" Cherry N1°58'E 8.82' to Fd. 1/2" CIR #11192

12 - 5/8" capped iron #12581 Set Blue Carsonite Post with Loc. tag 1' SE N88°43'W 52.92' (53' - P & R) to Fd. 5/8" CIR. S45°E 52.05' to set N & T in SW side 31" R. Maple S33°W 8.82' to set N & T in NW 15" Willow N34°E 86.69' to set N & T in NW side 15" R. Pine

Signed by: Surveyor's Michigan License No .: 39088

Date:

OF MICHIG CRAIG W. McVEAN PROFESSIONAL SURVEYOR No. 39088 A OFE SSION