

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Benzie
(County)
Located In
Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Section
4. Lot No:
5. Private Claims:

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and a black dot at row 7, column B.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1968 - Department of Conservation Survey Map - K. J. Ostling - Found iron bar, probably by Cade.
- 1988 - LCRC #248 - Carl F. Roser - Found 3/4" iron that fits K. Ostling's Survey;
- 2006 - Recorded Survey 2006S-00059 John B. Smendzuik - Found 5/8" rebar 1' deep, ±1' N. of centerline of gravel road.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

B7 - 1/4 Corner common to Sections 18 & 19, T26N, R13W - Found 5/8" x 2.5' long smooth iron rod, down 1.2' below grade. 2' ±1' North of centerline E-W gravel road. No GLO evidence. Fits stump remains of witnesses #3 and #8. Fits witnesses by Roser and Smendzuik. 5/8" smooth iron rod is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B7 - Replaced 5/8" x 2.5' iron rod with stamped 3" Benzie Co. Remon. Brass Cap on 3/4" x 36" iron pipe encased in 4" x 36" concrete cylinder. - Down 0.6'
N29°W 61.65' to set Nail & Tag (N & T) at fd. nail in E side 8" S. Maple in clp. - 4 (#15)
N7°E 33.43' to fd. PK nail in W. side Power Pole (#13)
N64°E 55.04' to set N & T at fd. nail in SE side 15" R. Pine (#10)
S46°E 57.94' to set N & T at fd. nail in NE side Triple 14" Basswood (#14)



Signed by: Craig W. McVean
Surveyor's Michigan License No.: 39088

Date: 12/11/2007