

RAISED BY THE BERRIEN COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER MICHIGAN  
PUBLIC ACT 345 OF 1990  
*W. G. KAMER*  
4-04-95

BERRIEN COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

11/29/95 111W2012 477  
CORNER 44.00  
111W2012 477  
STATE FEE \$2.00

For corners in  
BERRIEN (County)  
Located In: Corner Code #

1. Public Land Survey	T 8S R 19W	A-9
Comments: T8S, R20, M9	T R	
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

RECORDED  
Nov 29 3 39 PM '95  
*Respectfully,  
J. G. KAMER*  
REGISTER OF DEEDS  
BERRIEN COUNTY, MICHIGAN  
Register of Deeds Stamp & File Number

I, JOHN G. KAMER, in a field survey on NOVEMBER 17, 19 95,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
(SEE BACK.)

*JOHN G. KAMER*  
MAR 27 1996  
COMMISSION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
FOUND 18" X 1" IRON WITH ILLEGIBLE CAP. THE PERPETUATION OF THIS CORNER AS EVIDENCED BY THE HISTORY  
OF WITNESS TIES APPEARS RELIABLE AND ACCURATE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
REMOVED 18" X 1" CAPPED IRON.  
SET STANDARD 3' X 4" CONCRETE MONUMENT WITH BRASS PLATE.  
SET NAIL W/TAG IN WOOD FENCE POST N 13° E 58.40'  
SET NAIL W/TAG IN WOOD FENCE POST N 84° E 15.23'  
SET NAIL W/TAG IN WOOD FENCE POST S 87° E 72.84'  
CENTER 2" FENCE POST WEST 1.61'  
CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THIS ORIGINAL CORNER.

Signed by *John G. KAMER*  
Surveyor's Michigan License No. 27449  
STATE OF MICHIGAN  
JOHN G. KAMER  
LAND SURVEYOR  
No. 27449  
Date 11-29-95  
FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
LIBER 3 PAGE 300

**SW Cor 19-8-19**

**A-9**

**Gallen Township**

**July 1829**

Lucius Lyon

Set Post on North Boundary Indiana  
15.55 Chains South E ¼ Post 24-8-20

Accessories:

18" Sugar Maple N39°W 39 Links

34" Beech N 51½°E 51 Links

**April 5, 1966**

G.L. Wightman

Found Large Stone Over Small Stone  
1023.20' South of Iron

**July 22, 1977**

M.R. Rushlow Survey Recorded Liber 1059, Pg. 276  
1023.05' South of E¼ Cor. 24-8-20

Accessories:

Fence Post N45°W 35.00'

Cherry Tree N35°W 70.19'

Centerline of Driveway North 14.0'

**February 3, 1992**

John G. Kamer (Indiana Survey)

Found 1" Iron Pipe

Fence Post N45°W 35.00'

Cherry Tree N35°W 70.19'

Centerline Driveway North 14'±

**March 7, 1995**

John G. Kamer

Found 1" Iron Pipe 1023.38' South  
of E ¼ Cor. 24-8-20

Accessories:

PK in PP S80°E 199.74'

NW Cor. House S55°E 156.04'

PK in Fence Cor. East 15.24'

PK in Wood Fence Post N20°E 58.30'