

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>34</u> T. <u>1</u> S., R. <u>4</u> W.		H-11
2. PROPERTY CONTROLLING IN SECTION <u>34</u> T. <u>1</u> S., R. <u>4</u> W.		E1/8 Cor., NE1/4
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Donald L. Bissell, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

H-11 Clay tile and plow point.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-11 Found 2" clay cylinder from information supplied by Davis Land Surveying, R.L.S. #17617.

E 1/8 Corner, NE 1/4, Section 34. Set halfway and on line between I-11 and I-12.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-11 N 1/4 Corner, Section 34	E 1/8 Corner, NE 1/4, Section 34
Set 1" Pipe with plastic cap.	Set 4" x 36" concrete monument with
N 35° W, 3.23', 16" Sassafrass, Spike & Tag	aluminum cap.
North, 41.46', 28" Cherry in fence cor.,	S 19° E, 37.52', 8" Elm, Spike and Tag
Spike & Tag	S 68° W, 35.91', 12" Hickory, Spike & Tag
S 80° E, 26.33', 7" R. Oak, Spike & Tag	N 47° E, 26.87', 6" Hickory, Spike & Tag
S 13° W, 25.78', 15" Cherry, Spike & Tag	S 34° E, 28.98', 3/4" Iron Pipe (Trail P.I
West, 1', fence	

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Donald L. Bissell DATE 11-19-80
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 18655

PAGE 5

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET