

1993

RECORDED

COMMISSION

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

OCT 6 9:47 AM '93

CLERK-REGISTER
CALHOUN COUNTY, MICH.
ANNE B. NORLANDER

For corners in
CALHOUN

(County)

Located In:

Corner Code ##

- 1. Public Land Survey T 1 S R 5 W A-11
 T _____ R _____
 T _____ R _____
 T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, DONALD J. DAVIS, in a field survey on SEPTEMBER 10, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

TILE SET IN RESURVEY IN 1891 BY GIFFORD.
12" SWAMP OAK S 75° E 56 LINKS.
12" SWAMP OAK S 38° E 42 LINKS.
IRON SET IN TILE BY H. ROGERS.

LIBER 1707 PAGE 275

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 5/8" IRON AND "T" IRON IN TILE WITH ROCKS AROUND UNDER PAVED ROAD.
RECORDED BY DE KEYSER IN 1973, LIBER 1027, PAGE 71.
UTILITY POLE S 66° E 54.26'.
18" OAK S 22° E 95.70'.
NE CORNER OF HOUSE S 45° W 123.35'.

CORNER ACCEPTED AS TRUE PERPETUATION OF RESURVEY CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET BERTISEN MONUMENT WITH BRASS CAP IN MONUMENT BOX.
NAIL & TAG 40" MAPLE S 70° E 69.12'.
NAIL & TAG 12" HICKORY N 35° W 67.76'.
NAIL & TAG 36" MAPLE N 25° E 86.20'.
NE CORNER OF HOUSE S 45° W 123.32'.



Signed by Donald J. Davis
Surveyor's Michigan License No. 17617

Date SEPTEMBER 14, 1993