

MAR 30 1999

APPROVED

Date 9-16-98 *RRC*  
CALHOUN COUNTY  
REMONUMENTATION

CALHOUN COUNTY REMONUMENTATION SECTION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
CALHOUN COUNTY  
RECORDED

For corners in

<u>CALHOUN</u>	Located In:	Corner Code #
(County)		
LERROY TOWNSHIP		
1. Public Land Survey	T <u>3S</u> R <u>8W</u>	<u>M-10</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

25 SEP 1998 2:29:06 PM

ANNE B. NORLANDER  
CLERK - REGISTER OF DEEDS

LIBER **2062** PAGE **590**

Register of Deeds Stamp & File Number

I, ROBERT R. CARR, in a field survey on SEPTEMBER 3, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

EAST 1/4 POST OF SECTION 25

A. Description of original monument and accessories and/or subsequent restoration:

ROBERT CLARK JR., D.S. 1826 SET ORIGINAL CORNER  
F. HODGEMAN 1885, RESURVEY, FOUND STONE SET FOR CORNER,  
WITNESSES GONE, SET POST (TILE) WITH BRICK AND STONE  
AROUND, Y. OAK 3" WEST 47 LINKS.  
SURVEY BY DAVIS, P.S. NO. 17617, JOB NO. 868, 1975, 1/2" IRON WITH WITNESSES  
SURVEY BY CARR, P.S. NO. 20704, SEPTEMBER 1997, FOUND TILE FROM BEARING TREE  
FROM HODGEMAN STILL STANDING, SET BERNTSEN MONUMENT AND MONUMENT  
BOX OVER TILE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND BERNTSEN MONUMENT IN MONUMENT BOX AND CHECKED WITNESSES.

DAVIS IRON IS S80° ±E 5.72 FEET.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BERNTSEN REMONUMENTATION MONUMENT STAMPED 20704  
1/2" IRON S80° ±E 5.72 FEET  
14" W. CHERRY, S76°E 39.68 FEET, SET SPOTTER  
20" MAPLE, N59°E 47.75 FEET, SET SPOTTER  
UTILITY POLE, N20°W 102.96 FEET  
40" OAK, WEST 31 FEET TO CENTER  
28" OAK WEST 26 FEET TO CENTER

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER



Signed by *Robert R. Carr*  
Surveyor's Michigan License No. ROBERT R. CARR 20704

Date SEPTEMBER 16, 1998