

APPROVED

Date 11/17/99 PRC
CALHOUN COUNTY
REMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
CALHOUN COUNTY
RECORDED

For corners in

CALHOUN
(County)
CLARENDON TWP.

Located In: Corner Code #

17 DEC 1999 2:44:35 PM

ANNE D. NORLANDER
CLERK - REGISTER OF DEEDS

LIBER **2186** PAGE **1**

Register of Deeds Stamp & File Number

1. Public Land Survey

T4S R5 W D-9
T R
T R
T R
S T R
S T R
S T R
S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Frederick J. Cutcher, in a field survey on August 24, 19 99 do hereby
state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1
and 2 above were in conformance with regulations and rules therefore as required in the current manual
of survey instructions of the United States Department of the Interior, Bureau of Land Management or
by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;
established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., 1825: 16" Sugar N. 50-1/2° E. 229 lks.; 15" Sugar S. 55-3/4° E. 503 lks.

Cutcher, 1980: Found 1/2" iron in centerline E/W road in line with fence to North and to South; 12" Maple S. 5° W. 32.25'; 12" Oak S. 50°
W. 48.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 18" iron 4" below road surface in centerline E/W road in line with fence/tree row to North and South.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced iron found with Berntsen Monument in Monument Box and is accepted as the best available evidence of the position of the
original corner.

Nail and Spotter 18" Twin Maple North 32.79'; Nail and Spotter 36" Maple S. 40° W. 31.81'; Nail and Spotter 18" Ash S. 10° W. 32.12';
Nail and spotter 24" Walnut S. 48° E. 47.26';

Signed by Frederick J. Cutcher
Surveyor's Michigan License No. 24592

Date 11/15/99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197
REVISED MAY 14, 197
REVISED JAN., 198
REVISED OCT., 199

SURVEY &
REMONUMENTATION

MAR 13 2000

SECTION

