

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 4 ^{XX} S., R. 8 ^{XX} W.	D9, E9, F9
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gary C. Bilow do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on February 14, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

From Road Commission Records

D9 Tile/Stone S17°W, 22.11 ft., 16" Cherry; S25°W, 19 ft., Cherry; S80°E, 93 ft., 15" Butternut	E9 Iron Pipe No Witnesses	F9 Tile S28°W, 8.25 ft., 20" Elm N34°E, 22.11 ft., 12" Ash
--	---------------------------------	---

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D9 Found stone in road at original ground surface with broken brick and small stones around it. Found stump of witness tree S25°W.	E9 Found 2" T-Iron pipe and old witness post 12" below mud.	F9 Found 1-1/4" iron pipe surrounded by rocks, at intersection of fences.
---	--	--

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D9 Replaced stone with 1" x 30" pipe with 4" aluminum cap over 1/2" x 18" pipe, 10" below road surface. N19°E, 30.40 ft., nail & RP tag in 7" Cherry; S7°W, 81.65 ft., nail & RP tag in PP; S64°W, 48.60 ft., nail & RP tag in 15" twin Cherry; N64°N, 63.94 ft., nail & RP tag in 16" triple Cherry.	E9 Raised old iron pipe with 1" by 6" iron pipe with 4" aluminum cap. N88°W, 21.02 ft., nail & RP tag in clump Maple; N46°W, 51.21 ft., nail & RP tag in clump Maple; N76°E, 42.51 ft., nail & RP tag in 7" Ash; S22°W, 9.20 ft., nail & RP tag in clump Maple.	F9 Replace 1-1/4" iron pipe with 1" x 36" iron pipe with 4" aluminum cap. N66°W, 40.03 ft., nail & RP tag in 12" Maple; S24°W, 11.16 ft., nail & RP tag in 14" Maple; S4°W, 62.93 ft., nail & RP tag in 14" Oak; N88°E, 16.45 ft., nail & RP tag in 7" Elm.
--	--	--

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Bilow DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM736
DOUGLASS BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS