

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

CHIPPENAW CO.

3 CORNERS

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
2. PROPERTY CONTROLLING IN SECTION 5	T. 41 N. 6 S. 6 R. 6 E. 4, 5, 7 W. 4, 5, 7	
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 3-16, 1989, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- 4 N.W. 1/16 Corner of Section 5. Not previously set.
- 5 North 1/16 Corner of Section 5. Not previously set.
- 7 North 1/16 Corner on East side of Section 5. Not previously set.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 4 Corner set at center of N.W. 1/4 of Section 5 by closed traverse.
- 5 Corner set midpoint on line between North 1/4 Corner and computed Center Corner of Section 5.
- 7 Corner set midpoint on line between East 1/4 Corner and N.E. Corner of Section 5.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR Monuments at all three corners, cap is broken at 4.

- |                          |                               |                             |
|--------------------------|-------------------------------|-----------------------------|
| 4 6" Cedar, N32°W, 23.7' | 5 6" W. Birch, S89°E, 37.9'   | 7 14" Cedar, N40°E, 231.35' |
| 6" Cedar, N81°W, 18.0'   | 14" W. Birch, N6 1/2°W, 15.8' | 12" Cedar, N54°W, 192.50'   |
| 6" Cedar, S19°E, 35.1'   | 7" Cedar, N60°W, 15.7'        | 12" Cedar, S88°W, 201.50'   |
| 6" Cedar, S78°E, 20.2'   | 7" W. Birch, S68°W, 18.4'     | 12" Cedar, S78°W, 203.50'   |

SIGNED BY Gerald L. Wiggins

DATE 3-16-89

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_


CHIEF OF SURVEY PARTY

DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET