

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Chippewa	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 9 T 42N R 2E	8
	S 9 T 42N R 2E	11
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 11 08/19/2009 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 9) West 1/16 corner, Section 9. Not established in the original survey.

(11-Sec. 9) Southwest 1/16 corner, Section 9. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 9) Established the corner midway and on a straight line between Quarter corner 1325.89' west and Center of Section 9 1325.89' east.

(11-Sec. 9) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx60" I.pipe with 4" alum. MDNR cap made firm with poured concrete.  
Set measuring nail with MDNR tag in the side of:  
Power pole 376 N80W 90.6'  
8" Spruce S30E 7.7' mrkd "W1/16 BT"  
9" W.Birch N55E 33.1' do  
12" Sugar N41E 56.85' do  
Bearings are magnetic.

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
7" Sugar S88W 3.25' mrkd "SW1/16 BT"  
6" Sugar S25E 33.9' do  
5" triple Sugar N66E 14.9' do  
9" twin Sugar N09E 48.5' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/15/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

