

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Chippewa

Drummond Is.

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	T. 42 N. R. 5 E.	I-12
2. PROPERTY CONTROLLING IN SECTION.....	T. S. R. W.	
3. MISCELLANEOUS PROPERTY IN SECTION.....	T. S. R. W.	
4. LOT NO., RECORDED PLAT.....		
5. PRIVATE CLAIMS.....		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Duckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 6/19 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 1972, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
Original 4" Corner placed by John Mullett, D.S., Sept. 8, 1845.
Bearings were:

Cedar 12" S17°W 7 Links
Pine 10" N60°E 9 Links

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
Found 3/4" Iron and Squared Wood Post, set by unknown Surveyor.
Found an older, Cedar Post on ground. Old blazed lines running South, East, and West from Corner, approx. 17 yrs old.
Found no evidence of original witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminum cap at Corner.
New Bearings:

22" W. Pine S56°W 23.9'
12" Cedar N15°E 36.6'
9" W. Pine S83°E 32.2'

SIGNED BY: Billy D. Duckler DATE: 10/25/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY: _____ DATE: _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY: _____ DATE: _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____