

SURVEY & REMONUMENTATION

FEB 23 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Chippewa County Remonumentation Corner

For corners in

Chippewa County Located in: Corner Code #

1. Public Land Survey T44N R1W G-10
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

\$7.00 LAND CORNER

\$2.00 NSSR
2 FEB 2001 3:49:39 PM Receipt #1103
RECEIVED FOR RECORD
CHIPPewa COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 11 PAGE 192

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on November 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-10 ¼ Corner Common to Sections 27 & 28, T44N, R1W.

1845 - Original corner established by James H. Mullett.

Witnesses: Tamarack 10, S29°W 12 links - Tamarack 8, N39°E 17 links.

1991 - Keith R. Waters, P.S. 33142, LCRC Liber 7, page 344, Chippewa County corner records. Found no evidence of corner. Reestablished corner by single proportionate measurement between Northwest and Southwest corners of Section 27. Set a ½" iron with cap L.S. 33142. Witnesses:

4" Elm, S47°E 63.30'

8" Aspen, S07°W 160.60'

10" Aspen, S45°W 49.45'

5" Elm, WEST 77.87'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a ½" iron with cap L.S. 33142 and all record bearing trees as called for in the above mentioned 1991 LCRC.

Replaced the found iron with a ¾" rebar and plastic Chippewa County Remonumentation cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a ¾" x 24" rebar with a plastic Chippewa County Remonumentation cap at the corner location, replacing a found ½" iron with cap L.S. 33142. Corner falls on the east edge of a north-south 2 track road.

Witnesses:

Nail in blazed 8" Elm, WEST 77.87' (previous witness, could not check measurement due to hunting shack in the way)

Nail and plastic witness tag #33142 in blazed 8" Elm, N48°W 179.16'

Nail and plastic witness tag #33142 in blazed 8" Elm, S42°E 63.27'

Nail and plastic witness tag #33142 in blazed 10" Aspen, S08°W 160.54'

Nail and plastic witness tag #33142 in blazed 12" Aspen, S45°W 49.52'

Signed by Keith R. Waters

Date 12-29-00

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1985