

FEB 23 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

SECTION

For corners in

Chippewa County

Located in:

Corner Code #

- | | | | | |
|-------------------------|---|------|-----|------|
| 1. Public Land Survey | | T44N | R1W | G-12 |
| | | T | R | |
| | | T | R | |
| | | T | R | |
| 2. Property Controlling | S | T | R | |
| in Section | S | T | R | |
| 3. Miscellaneous | S | T | R | |
| Property in Sec. | S | T | R | |

\$7.00 LAND CORNER

\$2.00 MSSR

2 FEB 2001 3:41:46 PM Receipt #1103

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 11 PAGE 178

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Keith R. Waters, in a field survey on November 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-12 1/4 Corner Common to Sections 33 & 34, T44N, R1W.

1845 - Original corner established by James H. Mullett.

Witnesses: Spruce 10, S87°W 26 links - Cedar 4, S71°E 15 links.

1896 - Chippewa County Surveyor Frederick H. Brown, RLS 944. Notes for Section 33 indicate that that "the corners in this section are those as made by Kenworthy and no original corners to be found when I came there in 1896." A drawing of Section 34 shows a distance of 5260 feet on the west side, with distances of 2630 feet for each half mile.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program. Found no evidence of the corner. Reestablished corner 33 feet west of a corner fence post, on the extension of the fence line to the east. Corner falls in the centerline of an old north-south road bed, on line between the section corner at G-11 2640.73 feet to the north and the standard section corner on the township line at G-13 2632.70 feet to the south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/4" x 24" rebar with a stamped aluminum Chippewa County Remonumentation cap at the corner location, which falls in the centerline of an old north-south road bed, 33 feet west of an old corner fence post. Corner is on line with a fence line and overhead power line to the east and is 9'± south of a ditch line to the west.

Witnesses:

Nail and plastic witness tag #33142 in Power Pole (122), N80°W 342.32'

Nail and plastic witness tag #33142 in Power Pole (123), S86°E 34.06'

Nail and plastic witness tag #33142 in top center of Fence Post, S38°E 61.05'

Nail and plastic witness tag #33142 in blazed 10" Aspen, N16°E 81.94'

Signed by Keith R. Waters

Date 12-29-00

Surveyor's Michigan License No. 33142

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

