LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Cornet , 00 LAND CORNER

For corners in

Chippewa County	Locate	d in: C	orner Code#
1, Public Land Survey		T44N R1W I- T R T R T R	12
2. Property Controlling in Section	S S	T REMONUM	EY &
Miscellaneous Property in Sec.	S S	TR	3 2001

\$2.00 MSSR 2 FEB 2001 3:48:47 PM Receipt #1103 RECEIVED FOR RECORD CHIPPEWA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 11 PAGE 189

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims

SECTION

I, Keith R. Waters, in a field survey on November 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above re in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below;

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

D E 2 3 6 7 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

1-12 1/4 Corner Common to Sections 34 & 35, T44N, R1W.

1845 - Original corner established by James H. Mullett. Witnesses: Fir 4, S35°E 13 links - Fir 4, S60°W 13 links.

1896 - Chippewa County Surveyor Frederick H. Brown, RLS 944. Drawing of Section 34 shows the East 1/4

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

EE OVUMEN TO THE PROPERTY OF T Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program.

Found no evidence of the original corner. Reestablished corner on line between the section corner at I-11 to the north and the standard corner on the township line at I-13 to the south, at record County Surveyor distance (2630 feet) from said corner at I-11, on the extension of fence lines east and west. The distance to said standard corner at I-13 is 2639 feet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/1" x 24" rebar with a plastic Chippewa County Remonumentation cap at the corner location, which falls 4'± west of the centerline of a north-south gravel road (Hancock Road) on line with fence and power lines east and west.

Nail and plastic witness tag #33142 in Power Pole (PD3/54A/6), N04°W 651.45'

Nail and plastic witness tag #33142 in Power Pole, EAST 136.14'

Nail and plastic witness tag #33142 in Triple 16" Red Oak, S65°E 286,03'

Nail and plastic witness tag #33142 in Corner Fence Post, WEST 25.30'

ATE OF MICHIGAN KEEH R. MARERS PROJECTIONAL SURVEYOR No. 33142 efficient and a ten LOFESSIONS

Signed by Keite R. Waln

Date (2-29-00

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983
REVISED CCT. 1985

BUUK 11 PAGE 189

T44N R1W I-12