

MAY 28 1997

COMMISSION CHIPPEWA COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 \$7.00 LAND CORNER

For corners in

Chippewa	Located In:	Corner Code #
(County)		
1. Public Land Survey	T44N R2W	C-5
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

\$2.00 HSSR
2/28/1997 3:58:53 PM Receipt #226
RECEIVED FOR RECORD
CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 9 PAGE 384

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Keith R. Waters, in a field survey on 06/10, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

C-5 Corner Common to Sections 7, 8, 17, & 18, Town 44 North, Range 2 West

1845 - Original ties to set post: Aspen 20, S37°E 50 links - White Pine 10, N14°W 50 links.

1907 - County Surveyor Frederick H. Brown notes indicate this is a "Carleton corner."

Circa 1920's - County Surveyor notes indicate a cement monument. Witnesses: Pole, N47°30'E 36' - Bolt, West 27'.

Circa 1970's - Harry W. Goodwin, RLS 5434, Certificate of Survey. Sketch shows this as an existing corner. No other information is shown.

1974 - Lawrence R. Feindt, RLS 21566, Certificate of Survey. The southwest corner of Section 8 is shown on drawing. A bearing is shown on the line between Sections 7 & 8, no other information is given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a 1/2" iron bar in a monument box 8 feet west of the centerline of Mackinac Trail. Also found a large, badly bent iron pipe approximately 27.7 feet west of the iron in monument box, which appears to occupy the position of the bolt shown as a witness in the above mentioned County Surveyor notes. Distances to other corners in the area check well with those as shown in above mentioned Frederick H. Brown notes.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1/2" iron bar in a monument box 8 feet west of the centerline of Mackinac Trail, at the intersection of a seasonal road to the east. Witnesses:

Power Pole (RU1-34), N72°W 89.28'

Power Pole (34-M), N84°W 177.68'

Southeast Corner of Concrete Block Building, S48°W 142.95'

Power Pole (RU1-33), S20°W 223.95'

Note: Unless noted otherwise, distances are to a nail/tag #33142 in the side of the witness object. Bearings are compass bearings corrected for declination.

Signed by Keith R. Waters
Surveyor's Michigan License No. 33142

Date 12-30-96

