

SURVEY & REMONUMENTATION

CHIPPEWA COUNTY REMONUMENTATION CORNER

APR 26 1995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in CHIPPEWA COMMISSION

Located In: _____ Corner Code ##

1. Public Land Survey T 45N R 1W K-7

2. Property Controlling in Section S _____ T _____ R _____

3. Miscellaneous Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____



\$ 7.00 LAND CORNER
\$ 2.00 MSSR
19 JAN 95 4:17 P.M. RECEIPT# 2266
RECEIVED FOR RECORD
CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Keith R. Waters, in a field survey on February 21, 1994
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-7 Corner Common to Sections 13, 14, 23, & 24, T45N, R1W.

Original ties to post: Hemlock 20, N59°W 10 links Cedar 18, S27°E 16 links.
1965 - Highway Department, as recorded in liber 3, page 222, Chippewa County corner records. Found 1" iron pipe and squared post.

1974 - Corner location is shown on a sketch of subdivision of Section 13, T45N, R1W, by DNR surveyor Billy Buckler, RLS 8887.

1989 - Corner is shown on a survey drawing by William Karr, P.S. 27450. Found 1" iron pipe.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-7 (T45N, R1W)

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a 1" iron pipe with a 4" aluminum DNR cap approximately 19 feet north of the centerline of an east-west 2-track road (15 Mile Road). Cap is stamped RLS 8887, dated 5-29-74. Distance to section corner to the east fits very well with old County Surveyor notes. Accepted corner as found and established new bearing trees.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-7 (T45N, R1W)

Corner is a 1" iron pipe with a 4" aluminum DNR cap 19 feet north of the centerline of an east-west 2-track road (15 Mile Road). Witnesses:

7" Red Maple, N20°E 10.80'
4" Cedar, N85°E 35.86'
6" Cedar, S18°E 53.58'
7" Cedar, S06°W 43.19'

Note: Distances are to a nail and tag in the side of the tree. Trees are blazed and painted. Bearings are compass bearings corrected for declination.

Signed by Keith R. Waters Date 12-23-94

Surveyor's Michigan License No. 33142