

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
Chippewa County Remonumentation Corner

SECTION  
For corners in

Chippewa County Located in: Corner Code #

1. Public Land Survey T46N R7W H-11  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R  
4. Lot No. , Recorded Plat  
5. Private Claims

BOOK 11 PAGE 106

\$7.00 LAND CORNER

\$2.00 MSSR

23 FEB 2000 4:29:42 PM Receipt #21175

RECEIVED FOR RECORD

CHIPPWEA COUNTY - STATE OF MICHIGAN  
SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on November 13, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-11 ¼ Corner Common to Sections 27 & 34, T46N, R7W

1850 - Original corner established by Well Burt, a spruce post.

Witnesses: Spruce 6, S65½°E 12 links - Spruce 8, N31°W 08 links.

Found no evidence of subsequent restoration of this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a squared cedar post, quite rotted, at the intersection of lines of old steel fence posts to the north and to the east. Found post is 2670.8 feet from section corner I-11 to the east, 2687.2 feet from section corner G-11 to the west, and is 0.7 feet south of a straight line between said section corners. The GLO notes indicate this corner midway between section corners 2673 feet east and west. Accepted the found post as the best evidence of the original corner location and replaced it with a ¾" rebar and stamped aluminum Chippewa County Remonumentation cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a ¾" x 24" rebar with a stamped aluminum Chippewa County Remonumentation cap at the corner location, replacing a found squared cedar post.

Witnesses:

Nail and tag #33142 in 6" blazed Tamarack, N15°W 4.98'

Nail and tag #33142 in 9" blazed Cedar, N80°W 5.62'

Nail and tag #33142 in 6" blazed Cedar, S60°W 26.33'

Nail and tag #33142 in 7" blazed Spruce, S36°W 27.70'

Signed by Keith R. Waters

Date 12-29-99

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995