

SURVEY & REMONUMENTATION

MAR 09 1894

Chippewa County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD
CHIPPEWA COUNTY
STATE OF MICHIGAN

93 DEC 14 PM 4: 26

COMMISSION

For corners in

Chippewa

(County)

Located In:

Corner Code #

1. Public Land Survey

T 46N R 1E

B-5

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

J. Ryan Malott

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

1. William L. Karr , in a field survey on November 29 , 19 93

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B-5) 1/4 Corner Common to Sections 7 & 18, (T46N-R1E)

This corner was recorded by R.H. Larsen, R.L.S. in Liber 2, Page 188 of the Chippewa County Corner Records as a 3/4" square iron bar with the following witnesses:

Telephone Pole N51°E 34.10'

Telephone Pole N41°W 29.33'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B-5) This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 3/4" iron in monument box. All witnesses were gone due to construction of M-129. Accepted corner position as found and added four new witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B-5) Corner is a 3/4" iron in a monument box in the center of M-129 and on the centerline of Eight Mile Road.

Witnesses: Punch hole in center of concrete

right-of-way marker

N63°E 57.15'

Punch hole in center of concrete

right-of-way marker


S65°E 79.34'

Power Pole (#14)

S23°W 204.95'

Power Pole

N63°W 67.75'



Signed by William L. Karr

Date 12/14/93

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless noted.