

MAY 28 1997

COMMISSION

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

\$7.00 LAND CORNER

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey

T46N R1E

D-9

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No.

, Recorded Plat

5. Private Claims

\$2.00 MSSR

2/28/1997 3:12:01 PM

Receipt #217

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 9 PAGE 374

Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on December 4, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D-9) 1/4 Corner Common to Sections 20 & 29, T. 46 N., R. 1E.

1845 J.H. Mullett set post in Original Survey.

14" Fir N44E 25 lks

8" Fir S30W 24 lks

1904 F.H. Brown in records in County Surveyors Office for a survey of section 29 shows the mile on the North side of the section as 5380' and divided up evenly. Brown makes no mention of evidence of the 1/4 corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D-9) 1/4 Corner Common to Sections 20 & 29, T. 46 N., R. 1E.

This corner is being reestablished as part of the Chippewa County Remonumentation Program.

Found no evidence of the original corner or subsequent restoration. The mile on the North side of section 29 measures 5358'. The North and South 1/4 line fences are offset by 11.5'. The 1/4 line fence to the South is 2640' East of the West section corner.

Did not consider fences to be evidence of a perpetuation of the corner position and set the 1/4 corner midway and on line between the section corners to the East and West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D-9) 1/4 Corner Common to Sections 20 & 29, T. 46 N., R. 1E.

Corner is a 3/4" x 24" re-bar with plastic Chippewa County Remonumentation cap North of the centerline of West gravel road. Corner is set 0.5' below grade.

Witnesses:	Fence Post	N 09° E	21.43'
	Utility Pole	S 45° W	65.07'
	Fence Post	S 72° W	90.14'
	30" Burr Oak	N 71° W	89.73'

Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

*William L. Karr*

Date 12-30-96

Surveyor's Michigan License No. 27450

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995