

**SURVEY &
REMONUMENTATION**

APR 27 1995

CHIPPEWA COUNTY REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 46N R 1E

K-6

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

\$ 7.00 LAND CORNER

\$ 2.00 MSSR

5 DEC 94 12:11 P.M. RECEIPT# 1517

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on October 19, 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K-6) 1/4 Corner to Sections 13 & 14, T.46 N., R.1 E.

1845: J. Mullett set 1/4 section post B. Ash 10 N75W 38

Fir 10 N83E 30

1982 W.L. Karr re-established corner mid-way and on line between the NE and SE corners of Section 14 and set a 1/2"x 18" iron with cap No.27450.

Recorded in L.6 of corners, P.370.

Witnesses: Centerline 2-track to East North 37.5'
Fenceline to West North 17.2'
North tree of twin Willow S42E 39.58'
Phone Box N88W 30.20'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


(K-6) This corner is being perpetuated as part of the Chippewa County Remonumentation program.

Found no evidence of original corner position. Found the 1/2" iron as recorded in L. 6, P.370 and Willow witness. Corner falls on the extension of a fence-line to the East. Accepted corner position as found and replaced with a 3/4"x 24" iron.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K-6) Corner is a 3/4"x 24" iron with plastic "Chippewa County Remonumentation" cap, 0.4' below surface in centerline of Lower Hay Lake Road.

Witnesses: P. Pole N86°W 41.47'
8" Willow N29°E 56.75'
Corner fence post S87°E 30.38'
N'ly stem (19") of twin Willow S42°E 39.52'



Signed by

William L. Karr

Date

12/2/94

Surveyor's Michigan License No. 27450

723-12

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless noted.