

## Chippewa County Remonumentation Corner

RECEIVED FOR RECORD  
CHIPPEWA COUNTY  
STATE OF MICHIGANLAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

93 NOV 31 AM 9:54

For corners in

Chippewa

(County)

Located In:

Corner Code #

## 1. Public Land Survey

#1  
T 46N R 1E K1/L1 Same  
T 47N R 1E K13/L13/Corner  
T R  
T R  
T R

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

J. Roger Malott  
REGISTER OF DEEDSSURVEY &  
REMONUMENTATION

JUL 22 1999

Register of Deeds Stamp &amp; File Number

## 4. Lot No. , Recorded Plat

## 5. Private Claims

I, William L. Karr, in a field survey on August 2, 19 93,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

## A. Description of original monument and accessories and/or subsequent restoration:

(K-1/L-1) Meander Corner Sections 1 and 36, T46N-R1E/T47N-R1E

1840 William A. Burt, set post.  
20" Maple N81°W 80 links

1946-1959 David Eagle Sub, Liber 6, Page 9 of Plats  
Eagle's Nest Sub, Liber 7, Page 5 of Plats

- Section line is shown on both plats as being 33' off right-of-way lines.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K-1/L-1) This corner is being reestablished as part of the Chippewa County  
Remonumentation Program.

Found existing monumentation of South line of Eagle's Nest Subdivision and North line  
of David Eagle Subdivision.

Reestablished corner position at GLO distance Easterly of Northwest corner Section 1,  
using a split of the distance between the Southeast and Northeast corners of the  
Subdivisions to determine direction.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K-1/L-1) Corner is a 3/4" x 48" iron with stamped 2 1/2" diameter aluminum cap  
(Chippewa County Monumentation) P.S. 27450. Corner falls in low grassy area along  
the St. Mary's River, 85' more or less West of the edge of the water.

Witnesses: 21" White Pine N52°W 214.40'  
Corp. of Engineers survey mark "CHW-065 1988"  
3 1/2" diameter aluminum cap in monument box S56°W 96.44'  
1 1/4" pipe in concrete (Northeast corner David Eagle Subdivision) S79°W 190.86'  
16" Spruce N86°W 233.12'  
1/2" iron L.S. 27450 (Southeast corner Eagles Nest Subdivision) N80°W 177.19'

Signed by

William L. Karr

Date

11/12/93

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination.  
Distances are to a nail in side of witness objects unless noted.

L. 8 P. 11

Other code 1

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19  
REVISED MAY 14, 19  
REVISED JAN., 19

