## REMONUMENTATION

CHIPPEWA COUNTY REMONUMENTATION CORNER

APR 27 1995

## For corners COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa		Located In:	Corner Code ##
	(County)		30.1101 3343 7.
1.	Public Land Survey	T47N R 2E	E-11/F-11
		T R T R	Other)
2.	Property Controlling in Section	S T R S T R	#5
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	[
		Descripted Dist	

\$ 7.00 LAND CORNER \$ 2.00 MSSR RECEIPT# 831 24 OCT 94 3:43 P.M. RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

KEITH R.

WATERS

IAND SURVEYOR

No.

4.	Lot No	Recorded Plat _	_
5.	Private Claims		

<sub>19</sub> 93 November 8 Keith R. Waters in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-11/F-11 Meander Corner Common to Sections 28 & 33, T47N, R2E

Original post was set at shore of Lake George, 32.5 chains (2145 feet) east of E OF MICHIGAN corner common to Sections 28,29,32, & 33.

Original ties:

Black Ash 12, N07°W 30 links Elm 10, 584°W 10 links Small island bears S78°E

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11/F-11 (T47N, R2E)

This corner is being re-established as part of the Chippewa County Remonumentation Program.

Re-established corner at Found no evidence of corner or its accessories. record GLO distance (2145 feet) east of corner common to Sections 28,29,32 & 33, on line with a found wood post at the west 1/16 corner common to Sections 28 & 33. Compass bearing to small island (Gem Island) checks well with that as shown in original notes. North-south position also works well with a found wood post at the northwest corner of Government Lot 4, Section 28. Corner falls approximately 60 feet from the shore of Lake George.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11/F-11 (T47N, R2E) Corner is a 3/4" x 24" rebar with  $3\frac{1}{4}$ " aluminum Chippewa County Remonumentation cap approximately 60 feet from the shore of Lake George. Witnesses:

10" Black Ash, N81°E 23.02' 8" Black Ash, S72°E 28.57' 10" Black Ash, S34°E 28.92'
12" Black Ash, S07°W 31.89'

Distances are to a nail and tag in Note: Trees are blazed the side of the tree. Bearings are compass bearings painted. corrected for declination. Distances are measured with EDM.

Signed by Kith R. Water	Date 10-18-94 10/2/94 Pace	_
Surveyor's Michigan License No. 33142	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN. 28, 19:	75
	WALLEST OF SERVED JAN. 49	83