FEB 23 2001

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

For corners in

Chippewa County	Located in:	Corner Code#
Public Land Survey     Reports Controlling	T47N T T T	R2E G-7/H-7 (MC) R R #010 R
in Section	S T S T	R R
3. Miscellaneous Property in Sec.	S T	R R

\$7.00 LAND CORNER

\$2.00 HSSR

9 FEB 2001 10:50:03 AM Receipt #1201 RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK **11** PAGE 247

Register of Deeds Stamp & File Number




, Recorded Plat

5. Private Claims

I, William L. Karr, P.S., in a field survey on December 8, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

(G-7/H-7) Meander Corner Common to Sections 15 and 21, Township 47 North, Range 2 East.

1845 J. Mullett, D.S. set post.

B. Ash 8 S74W 46

B. Ash 10 N44W 53

OVUMEN 1966 R.H. Larsen – notes corner as a 4" square post. 900 feet more or less East of Section corner 16, 15, 22 and

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (G-7/H-7) Meander Corner Common to Sections 15 and 21, Township 47 North, Range 2 East. This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found no evidence of the original corner or subsequent restoration. Reset corner at record GLO distance (1023.00 feet) East of Section corner using an index bearing for direction. Six separate 1/2 mile East - West lines were retraced to determine the index bearing.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (G-7/H-7) Meander Corner Common to Sections 15 and 21, Township 47 North, Range 2 East.

Corner is a 3/4" x 24" iron with stamped Chippewa County Remonumentation Corner cap and falls on brush line to West.

Witnesses:

は103303.		
Ash 6"	N16°É	16.15 feet
Ash 4"	S71°E	7.61 feet
Maple 14"	S38°W	35.62 feet
Ash 8"	N80°W	16.87 feet
Square Post	North	1.00 feet

Bearings are magnetic compass bearings. All distances are to a nail and tag in the side of the witness object unless otherwise noted.



William L. Karr,

Surveyor's Michigan License No. 27450

Date 17/29 00

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
FAGE 247 REVISED JAN., 1963
PAGE 247 REVISED OCT., 1995