

## SECTION

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**  
 Chippewa County Remonumentation Corner


For corners in

Chippewa County

Located in:

Corner Code #

- |                         |   |          |               |
|-------------------------|---|----------|---------------|
| 1. Public Land Survey   |   | T47N R2E | C-4           |
|                         |   | T R      |               |
|                         |   | T R      |               |
| 2. Property Controlling | S | T R      |               |
| in Section              | S | T R      |               |
| 3. Miscellaneous        | S | T R      |               |
| Property in Sec.        | S | T R      |               |
| 4. Lot No.              |   |          | Recorded Plat |
| 5. Private Claims       |   |          |               |



\$7.00 LAND CORNER

\$2.00 MSSR

9 FEB 2001 10:29:22 AM Receipt #1201

RECEIVED FOR RECORD

CHIPPWEA COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 11 PAGE 220

Register of Deeds Stamp &amp; File Number

I, Larry R. Rogers, P.S., in a field survey on December 13, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5		4		3		2				
3													
4		7	8		9		10		11		12		
5													
6		18	17		16		15		14		13		
7													
8		19	20		21		22		23		24		
9													
10		30	29		28		27		26		25		
11													
12		31	32		33		34		35		36		
13													

## A. Description of original monument and accessories and/or subsequent restoration:

(C-4) 1/4 Corner common to Sections 7 and 8, Township 47 North, Range 2 East.

John Mullett set original 1/4 section post in 1845. County surveyor records of unknown date indicate that the corner is a 1" x 30" drift bolt at intersection of county roads. Granger Engineering traverse notes dated 1980 indicate that a 1" iron was found bent 22" below grade. A 1/4" iron was placed over bent 1" iron at intersecting centerlines of county roads to North, East and West.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-4) 1/4 Corner common to Sections 7 and 8, Township 47 North, Range 2 East.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 1/2" iron 24" below grade at intersecting centerlines of county roads. Accepted corner position as found and placed 3/4" x 24" iron over 1/2" iron and established new witnesses.



## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-4) 1/4 Corner common to Sections 7 and 8, Township 47 North, Range 2 East.

Corner is a 3/4" x 24" iron at intersecting centerlines of county roads approximately 1" below grade. Monument box will be placed in Spring of 2001.

## Witnesses:

Utility Pole	N75°W	187.76 feet
Utility Pole SU1/27/29	N69°E	65.44 feet
8" Oak	S16°E	20.95 feet
8" Yellow Birch	S26°W	97.66 feet

Bearings are magnetic compass bearings. All distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

Larry R. Rogers, P.S.

Surveyor's Michigan License No. 29251

Date

29 DEC 2000