REMONUMENTATION

FEB 23 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

For corners in

Chippewa County	Located in:		Corner Code #
Public Land Survey	T47N T T T	R2E R R R	F-5
2. Property Controlling in Section S	S T S T	R R	
3. Miscellaneous S Property in Sec. S		R R	

\$7.00 LAND CORNER

\$2.00 MSSR

9 FEB 2001 10:36:10 AM Receipt #1201
RECEIVED FOR RECORD
CHIPPEWA COUNTY - STATE OF NICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 11 PAGE 238

Register of Deeds Stamp & File Number


4. Lot No.

, Recorded Plat

5. Private Claims

I, Larry R. Rogers, P.S., in a field survey on December 13, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



LARRY R.

ROGERS

NO.

29251

LAND S

SED

A. Description of original monument and accessories and/or subsequent restoration:

(F-5) 1/4 Corner common to Section 9 and 16, Township 47 North, Range 2 East.

John Mullett placed the original 1/4 Section post in 1845 and established the following witnesses. Spruce 16 S66E 18, and a Spruce 10 N87W 28. No specific reference to this corner was found in County Surveyor records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (F-5) 1/4 Corner common to Section 9 and 16, Township 47 North, Range 2 East. This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner or any subsequent restoration. Re-established corner position using single proportionate between the Southwest and Southeast corners of Section 9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (F-5) 1/4 Corner common to Section 9 and 16, Township 47 North, Range 2 East.
Corner is a 3/4" x 24" iron with a stamped aluminum remonumentation cap 6" above grade, common approximately 250 feet North of North edge of a field.

Witnesses:

 4" Maple
 N70°W
 29.70 feet

 16" Maple
 N38°E
 33.38 feet

 16" White Birch
 S75°E
 33.65 feet

 7" Maple
 S55°W
 33.75 feet

Bearings are magnetic compass bearings. All distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

Larry R. Rogers, P.S. Surveyor's Michigan License No. 29251 Date 29 DEC 2000