## **SURVEY &** REMONUMENTATION

FEB 2 3 2001

## LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich, P.A. 1970 Chippewa County Remonumentation Corner \$7.00 LAND CORNER

For corners in

Chippewa County Located in: Corner Code # 1. Public Land Survey T47N R2F 1.2 Ţ R т R Ţ R 2. Property Controlling Т R in Section S Т R 3. Miscellaneous S R Property in Sec. 2

\$2.00 MSSR 9 FEB 2001 10:50:48 AM Receipt #1201

RECEIVED FOR RECORD CHIPPEWA COUNTY - STATE OF HICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS


PAGE 250 PANK 11

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat 5. Private Claims

I, Larry R. Rogers, P.S., in a field survey on December 08, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration: (I-2) 1/4 Corner common to Sections 3 and 2, Township 47 North, Range 2 East. John Mullett set original 1/4 section post in 1845. No specific reference to this corner was made in the County Surveyor records. On a certificate of survey by W.L. Karr, P.S. 27450 dated December 1997 he indicates that he established this corner midway and on line between the Northwest and Southwest corners of Section 2. A 3/4" iron with remonumentation cap was placed and the following witnesses were established:

8" Yellow Birch 14" Maple

N01°E S11°W 21.56 feet 29.79 feet 8" Yellow Birch

13" Yellow Birch

S33°F N53°W 15.91 feet 50.93 feet

08/00

MICHIG.

LARRY R.

ROGERS

NO.

29251

and Surveyor

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (I-2) 1/4 Corner common to Sections 3 and 2, Township 47 North, Range 2 East. This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

TO VOMENT Found 3/4" iron 2" above ground and all witnesses as indicated on Karr's certificate of survey. Accepted corner as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (I-2) 1/4 Corner common to Sections 3 and 2, Township 47 North, Range 2 East.

Corner is a 3/4" iron with plastic Chippewa County remonumentation cap 2" above grade.

Witnesses: 8" Yellow Birch 8" Yellow Birch

N01°E S33°E S11°W 21.56 feet

14" Maple

15.91 feet 29.79 feet

13" Yellow Birch

N53°W

50.93 feet

NSED LAND Bearings are magnetic compass bearings. All distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

Larry R. Rogers, P.S.

Surveyor's Michigan License No. 29251

DEC

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

ROOK THE PAGE TO PROFESSIONAL SURVEYORS, JAN. 28, 1971

PAGE TO PROFESSIONAL SURVEYORS JAN. 1983

REVISED JAN. 1983