

✓

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Chippewa COUNTY


T 49N R 7W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 28-29-32-33

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 8-30-71

WITNESSES TO CORNER..... 17" Red Pine (S32 NBT) S18°W 29.7'



9" Red Pine (S29 NBT) N34°W 21.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a 1" iron pipe, which appears to be in proper position. Found an original $\frac{1}{4}$ Corner, $\frac{1}{2}$ mile to East, record distance - 2650.0' and an original $\frac{1}{4}$ Corner, 2648.0' North.

Record distance was 2640.4'

A survey in 1939 by John A. Webb indicates this Sec. Cor. to be lost. I believe the corner was re-established at that time.

A borrow pit, North-East and an old logging grade, South-west, apparently removed both original witnesses.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE

9-22-71

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓