

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Chippewa

(County)

Located In:

Corner Code #

1. Public Land Survey

T 49N R 7W

C3

T R

T R

S T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Jul 25 2005

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 20\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C3) Corner common to Sections 5-6-7-8. 1849 - Established by Wells Burt, Deputy Surveyor: North between Sections 7 & 8 ...80.00 Set Cherry post corner of Sections 5,6,7,8. W.Pine 30 S75W 20 links, W.Pine 30 N44E 46 links. 1952 - Remonumented by Dean C. DeLaMater, RLS: This corner was pointed out to me by B. McIver, District Forester, of Newberry. Two original B.T.'s still in place, poor condition. Set 1" Pipe with 4" brass cap. 12" W.Pine N87E 87 links, 14" W.Pine S15E 93 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C3) Recovered the 1952 monument in good condition and at record bearing and distance from the 1952 W.Pine witnesses. The W.Pine NE is in good condition. The W.Pine SE is a stump. Left the monument in place and made new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C3) Found 1" ID I.pipe with 4" brass MI

Dept. of Conservation cap. Set

measuring nails in:

6" W.Pine N30E 22.5' mrd "S5 N8T"

8" W.Birch N39W 12.95' "S6 N8T"

18" W.Pine S39W 24.9' "S7 N8T"

5" W.Pine S51E 12.7' "S8 N8T"

Bearings are magnetic. Distances are to nail with tag.



Signed by Stephan J. Szyszkoski

Date 2/21/06

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995