

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Chippewa

(County)

Located In:

Corner Code #

1. Public Land Survey

T 49N R 7W

E2

T R

T R

S T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Aug 29 2005

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E2) Quarter corner common to Sections 4 and 5. 1849 - Established by Wells Burt, Deputy Surveyor: South Corrected between sections 4 & 5 ...39.66 Set maple post qr. section corner. Cedar 12 N85E 15 links, Y.Birch 14 N46W 24 links. ...79.66 Section corner. 1952 - Remonumented by D.C.DeLaMater RLS: This corner was pointed out to me by B.McTiver, District Forester, of Newberry. Corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor. Set 1" Pipe with 4" brass cap. 8" Spruce N86W 17 links, 6" Balsam N88E 74 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E2) Recovered the 1952 monument in good condition and at record bearing and distance from the 1952 witness trees, now both stumps with no markings visible. Left the monument in place and made new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E2) Found 1" ID I.pipe with 4" brass MI

Dept. of Conservation cap. Set

measuring nails in:

12" Spruce N83W 15.35' mrd "1/4S N8T"

5" W.Pine N40W 10.2' do

5" Maple S80E 13.2' do

5" Maple S10W 18.15' do

Bearings are magnetic. Distances are to nail with tag.



Signed by

Stephan J. Szyszkoski

Surveyor's Michigan License No.

33986

Date

2/21/06

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995