

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Chippewa

(County)

Located In:

Corner Code #

1. Public Land Survey

T 49N R 7W

F1

T 50N R 7W

F13 (same corner)

T R

S T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Jul 20 2005

I, Stephan J. Szyszkoski

, in a field survey on , 20 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F1) Quarter corner common to Section 4 T49N-R07W and Section 33 T50N-R07W. 1840 - Established by Wm.A.Burt, Deputy Surveyor: "West on South side of Sect. 33 ...40.00 Set qr. section post. Tamarack 16 N16E 10 links, Cedar 10 N63W 25 links. ...80.00 Set post corner of sections 32&33". 1952 - Remonumented by Dean C. DeLaMater, RLS: "This corner was pointed out to me by B.McTiver, District Forester, of Newberry. One original B.T. still in place, poor condition". Set 1" pipe with 4" brass cap. 9" Cedar S28W 22 links, 6" Cedar N78W 9 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F1) Recovered the 1952 monument in good condition and at record bearing and distance from the 1952 NBTs, both in good condition with overgrown blazes. Left the monument in place and made new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F1) Found 1" ID I.pipe with 4" brass MI

Dept. of Conservation cap. Set

measuring nails in:

10" Cedar N68W 6.2' mrkd "1/4S NBT" *

12" Cedar S27W 14.5' do *

12" Cedar S61E 9.75' do

8" Cedar N71E 18.0' do

Bearings are magnetic. Distances are to nail with tag. * denotes 1952 NBT.



Signed by

Stephan J. Szyszkoski

Surveyor's Michigan License No.

33986

Date

2/21/06

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995