

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

One Corner

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>50</u> N. <u>SE</u> R. <u>6</u> W.	E-2A
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-15, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

E-2A Witness Corner to Meander Corner, bet. Sec's. 4-5, on shore of Lake Superior.

Meander Corner set by Wells Burt, D.S. in 1849.

Bearings were:

W. Pine 18", S28 $\frac{1}{4}$ °E, 1.60 Chs. and Y. Pine 14", S11 $\frac{1}{2}$ °W, 1.84 Chs.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:


E-2A Placed witness corner to M. C. by proportionate distance bet. corners on lake shore one mile East and two miles West. Corner lies 149.0' South of record position of meander corner due to erosion of shore.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-2A Placed 1" pipe with 4" aluminium cap at the corner.

Bearings are: 14" W. Pine, S31°E, 41.6' and 18" W. Pine, S13°W, 36.5' and 14" W. Pine, S72°W, 44.8'

NOTE: See sketch on reverse side.



SIGNED BY Billy D. Buckler

DATE 8-25-75

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____

DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____