

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED
E 100 A 10
92-95
95 OCT -3 PM 2:48

REGISTER OF DEEDS
CLARE COUNTY
DONNA M. CARR

For corners in
CLARE
(County)

Located In:

Corner Code #

- | | | | | | |
|---|---|------------|---|-----------|------------|
| 1. Public Land Survey | T | <u>18N</u> | R | <u>3W</u> | <u>E-7</u> |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling
in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous
Property in Section | S | | T | R | |
| | S | | T | R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, MARK R. ROBISON, in a field survey on JULY, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1856 CANNON, POST
HEMLOCK 14 N45 1/2°W 40
HEMLOCK 18 S78°E 21

10-04 JOHNSON - MEAS 39.41 TO F-7 CSR

10-76 LAPHAM FD 4" PIPE W/WOOD HUB
(132) SURVEY
S45°W, 40.34 FENCE COR.
N45°W, 34.12 FENCE COR.
N45°E, 45.95 FENCE COR. (FD)

10-76 LAPHAM SAME AS ABOVE LCRC

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FD 4"x18" AXLE HUB SURROUNDED BY LARGE STONE. ENCOUNTERED VERY LARGE STONE AT 2 1/2' DEEP.
CORNER FALLS IN CENTER-LINE OF E-W ROAD AND 5' WEST OF CENTER-LINE OF N-S ROAD.
REC. 2612.55 (MEAS. 2611.88) WEST TO D-7, MEAS EAST 2618.39 (CSR 2601.06) TO F-7

APPROVED LAND CORNER

P.A. 345 of 1990

Clare County

Chairman Paul B. Loph

Date 10-3-95

This Corner established in Clare County Remonumentation Program.

See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-7, 16-17-20-21 SEC COR
SET 5/8"x18" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP.
ACCEPTED AS BEST AVAILABLE EVIDENCE OF ACCEPTED POSITION OF THE CORNER.
N45°W 39.78 N&T IN NEW FENCE POST (OLD POST REMOVED)
N45°E 45.95 N&T IN FENCE POST (OLD)
S60°W 63.38 N&T IN 8" ELM (MIDDLE OF TRIPLE ELM)
S40°E 78.04 N&T IN P.P.



Signed by Mark R. Robison
Surveyor's Michigan License No. 27458

Date 10-3-95