

CLINTON COUNTY

REMONUMENTATION

SECTION 9, WESTPHALIA TOWNSHIP

JAN 17 1996

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Clinton
(County)

COMMISSION

Located In:

Corner Code #

RECORDED

Dec 19 2 50 PM '95

RECORDS
CLINTON COUNTY, MICH.

LIBER 4, PAGE 120

Register of Deeds Stamp & File Number

1. Public Land Survey	T	<u>6N</u>	R	<u>4W</u>	<u>E-4</u>
	T		R		
	T		R		
	T		R		
2. Property Controlling	S		T		
In Section	S		T		
3. Miscellaneous	S		T		
Property In Section	S		T		

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Arden S. Pierson P.S., in a field survey on October 27, 1995,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original survey performed by Lucius Lyon DS 1927.
40.00 chains - set 1/2 mile post
23" Sugar - S34°E - 35 links
20" Lynn - S58°W - 31 links

Corner shown on Westphalia Amended Plats III and IV (by Chas. E.
Hollister in 1893).

(OVER)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1/4 Corner Common to Section 8 & 9, T6N, R4W. Found 3/4" pipe in
monument box (paved over). Removed pipe and monument box, found 3"
diameter pipe 24" below road surface. Set Standard Clinton County
Monument and monument box. Accepted 3/4" pipe in monument box as
a careful and faithful perpetuation of the position of the original
corner.

APPROVED BY
CLINTON COUNTY PEER GROUP
DATED 11/8/95
J. J. J.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

West 1/4 Corner, Section 9

*Standard Clinton County Monument in monument box
SW Corner Concrete Block Building - N73°E - 114.06'
NW Corner Concrete Block Building - N48°E - 153.10'
Nail & tag #13039 in SE Side Power Pole - N65°E - 32.75'
Nail & tag #13039 in North Side Service Pole - N90°W - 30.37'

*Standard Clinton County Monument is a 2 1/2" dia. steel tube
30" long with a stamped brass cap and a breakaway magnetic base.

Signed by Arden S. Pierson

Date November 4, 1995

Surveyor's Michigan License No. 13039

Certified Boundary Survey, Liber 1, Page 118, dated January 15, 1972 by Ron Helsel #18994, Fred White Engineering Company.

No witnesses.

LCRC, Liber 1, Page 499, dated October 25, 1972, by Fred White #12034.

Monument box.

4" Steel Anchor Post - West - 30.40'
Scott Tag, Power Pole - S30°W - 67.12'
Alpena, Michigan
P.K. Nail in Power Pole - N80°E - 32.93'

Clinton County Road Commission Alignment Field Notes related to U.S. Public Land Survey Corners, dated 1920+/-.

E-4: T6N, R4W, 1/4 corner common to Sections 8 & 9.
Stone not dug up.