

**SURVEY &
REMONUMENTATION**

MAR 29 2000

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in **SECTION**

STATE OF MICHIGAN
CRAWFORD COUNTY
RECORDED

<u>Crawford</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T <u>25N</u> R <u>2W</u>	<u>C-13</u>
2. Property Controlling in Section	S _____ T _____ R _____ S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____

17 AUG 99 12:29 P.M.

SANDRA MOORE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

LIBER 4 PAGE 03

I, Marvin E. Myers, In a field survey on March, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O - 1838 John Brink D.S. Mon. - Post 10" Pitch Pine N78°W 37 links. 10" Pitch Pine N51 1/2°E 28 links	George D. Henning R.L.S. Unrecorded survey December 1941 Mon: 1/2 buggy axle set in 1937 from the stumps of the original U.S. BT's, Position verified from chainage from North, East, and West. Wit: 16" Norway Pine N82°E 104.61' 6" Jack Pine N65°W 31.4'	10" Jack Pine S42°W 21.1'
George D. Henning R.L.S. Unrecorded survey February, 1942 Mon: 1/2 buggy axle Wit: 16" Norway Pine N82°E 1.16 1/2 6" Jack Pine N65°W 47 1/2	10" Jack Pine S42°W 32 14" White Pine S72 1/2°E 1.58	Plat of MOON RIVER HEIGHTS March 1964 by C.E. Ostling #12026 Mon - unknown Wit: none given
Plat of Johnston Acres by G. D. Henning Roscommon County Records, 1954 Mon: 1" x 1" x 36" iron in corner Wit: 16" Yellow Pine N82°E 76.9' 6" Jack Pine N66°W 30.7	10" Jack Pine S42°W 21.1' 14" White Pine S72 1/2°E 104.6'	Plat of Jonassen Subdivision by G.D. Henning, P.S. #2240 Mon - unknown Wit: unknown

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" x 1" x 36" iron (buggy axle)
Found 16" Yellow Pine N82°E 76.9' Found 10" Jack Pine S42°W 21.1'
Found 6" Jack Pine N66°W 30.7' Found 14" White Pine S72 1/2°E 104.6'
Accepted 1" iron buggy axle as a perpetuation of the Original Government Corner. Replaced 1" iron with Standard Roscommon County monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon: Standard Roscommon County Corner
Wit: Set nail & tag in 12" White Pine S72°E 48.86' Set nail & tag in Power Pole S08°E 51.78'
Set nail & tag in 16" Black Oak S53°W 31.92' Set Carsonite Post N42°W 25.98'

Signed by Marvin E. Myers
CRAWFORD COUNTY
Surveyor's Michigan License No. 21600
PEER GROUP APPROVAL
DATE June 7, 1999
Marvin E. Myers M.E.M.
Marvin E. Myers, P.S.
County Surveyor



Date June 9, 1999