

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey

T 26N R 1W B-5  
T 26N R 1W B-6

2. Property Controlling in Section

S T R  
S T R

3. Miscellaneous Property in Section

S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on July 6, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-5 G.L.O. D.A. Pettibone 1852 Set quarter section post

Wit: Pine 20" S58°E 17.5 links

Pine 20" N12°W 32 links

1978 Glenn A. Fauser P.S.#18657 Found a 1/2" bar for the corner.

Wit: 16" R. Pine N52°W 32.33'

P. Pole N62°E 18.65'

16" R. Pine S65°E 51.80'

SE Corner House S70°W 38.90'

NE Corner House N80°W 40.38'

B-6 1978 Glenn A. Fauser P.S.#18657 Found a 1" pipe for the corner.

Wit: 10" J. Pine S84°W 36.31'

8" J. Pine N45°W 15.29'

16" J. Pine N61°E 54.49'

5" J. Pine S14°E 66.48'

Centerline of trail South 29'

1997 Marvin Myers P.S. #31600 found 1/2" bar for corner same witnesses as above.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-5 Found 1/2" iron bar fitting Glenn A. Fauser's witnesses.

B-6 Found 1" pipe fitting Glenn A. Fauser's witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5 Set a 1" X 32" pipe w/ P.S. cap #33981 in place of found 1/2" iron bar.

Wit: P. Pole N64°E 18.69'

16" R. Pine S62°E 52.45'

SE Corner House S70°W 38.89'

NE Corner House N78°W 40.41'

B-6 Found 1" pipe added P.S. cap #33981

Wit: 10" J. Pine N39°W 15.30'

12" J. Pine West 36.50'

12" J. Pine N68°E 54.52'

12" J. Pine S08°E 66.44'

C.L. of trail South 34.4'±

Signed by:

Carl T. Kiiskila

Date:

2-5-07

Surveyor's Michigan License No.:

33981

