

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: _____ Located In _____ Corner Code # _____
Crawford
(County)

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 18 T 26N R 1W 6
S 18 T 26N R 1W 14
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on August 17, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18			17		16		15		14		13	
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - 1978 Glenn A. Fauser P.S. #18657 set a 1/2" rod for the corner while doing work for Consumers Power Co. in 1978. 14 - 1978 Glenn A. Fauser P.S. #18657 set a 1/2" rod for the corner while doing work for Consumers Power Co. in 1978.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

6 - Found 1/2" iron as set by Glenn A. Fauser 14 - Found 1/2" iron as set by Glenn A. Fauser

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - Found 1/2" iron rod added P.S. cap #33981 14 - Found 1/2" iron rod added P.S. cap #33981
Wit: 9" J. Pine N42°W 7.88' Wit: 6" Balsam S15°E 6.25'
13" J. Pine S40°E 19.00' 5" Balsam S80°E 15.98'
4" W. Pine N75°E 18.75' 4" Balsam N16°E 35.04'
4" W. Pine S74°W 37.51' 4" Balsam N54°W 6.78'

Signed by:

Carl T. Kiiskila

Date:

2-5-07

Surveyor's Michigan License No.:

33981

