

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Crawford Located In _____ Corner Code # _____
 (County)

- | | | | | | |
|--------------------------------------|---|-------------|---|------------|-------------|
| 1. Public Land Survey | T | <u>26 N</u> | R | <u>1 W</u> | D-12 |
| | T | _____ | R | _____ | _____ |
| 2. Property Controlling in Section | S | <u>32</u> | T | <u>26N</u> | R <u>1W</u> |
| | S | _____ | T | _____ | R _____ |
| 3. Miscellaneous Property in Section | S | _____ | T | _____ | R _____ |
| | S | _____ | T | _____ | R _____ |

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on October 6, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- | | |
|---|--|
| D-12 October 1971 Kenneth J. Ostling R.L.S. # 10068 set a 1" pipe at the intersection of the North-South and East -West ¼ lines.
Wit: 6" Balsam S51°W 16.6'
9" Balsam N22°W 16.0' | 9- October 1971 Kenneth J. Ostling R.L.S. # 10068 set a 1" pipe for the East 1/16 on the East -West ¼ line.
Wit: 21" R.Pine N39°W 126.9'
11" Black Oak N80°W 50.1'
11" Black Oak S02°E 6.3' |
|---|--|

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

- | | |
|---|---|
| D-12 Found a 1" pipe as set by K.J. Ostling | 9- Found a 1" pipe as set by K.J. Ostling |
|---|---|

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|---|---|
| D-12 1" pipe
Wit: 14" Maple N60°E 26.05'
8" W. Pine N20°E 16.87'
3" W. Pine N51°W 20.32'
16" Maple S43°E 76.42'
Red Top Post North 1'± | 9- 1" pipe
Wit: 6" W. Pine N67°E 19.28'
6" W. Pine N07°W 11.98'
10" W. Pine N65°W 29.04'
4" W. Pine N03°W 27.95'
Red Top Post East 1'± |
|---|---|

Signed by: Carl T. Kiiskila
 Surveyor's Michigan License No.: 33981

Date: 10/17/05

