

SURVEY &
REMONUMENTATION

APR 07 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION

Crawford

(County)

Located In:

Corner Code #

1. Public Land Survey Sec. 31 T 26 N R 4 W
Sec. 6 T 25 N R 4 W
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

B-13
B-1

STATE OF MICHIGAN
CRAWFORD COUNTY
RECORDED

19 DEC 97 2:38 P.M.

SANDRA MOORE
REGISTER OF DEEDS

Register of Deeds Stamp & File
Number

4. Lot No. , Recorded Plat

5. Private Claims

LIBER

3

PAGE 291

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Marvin E. Myers, in a field survey on September, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.

April 16, 1839

H. Brevoort D.S. &

James H. Mullet D.S.

Mon: Post

Wit: 10" Pine N37 1/2°E 30 links

12" Pine N09°W 11 links

Michigan Department of Conservation

Billy D. Buckler R.L.S. July 31, 1957

This corner established by proportionate measurement.

Mon: 1" pipe with 4" brass cap

Wit: 8" Black Oak N14°W 18 links

7" Black Oak S85°E 67 links

CRAWFORD COUNTY

PEER GROUP APPROVAL

DATE

8/16/1997

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe with remnants of a Conservation Department cap.

Found Oak stump N45°W 11.93'

Found Oak Stump S85°E 44.45'

Accepted 1" pipe as a reestablishment of the position of the Original Government corner.

Replaced pipe with Standard Crawford County monument.

Marvin E. Myers, P.S.

County Surveyor

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon - Standard Crawford County Monument

Set Nail & tag in N. side 4" Poplar 134° 16.54'

Set Nail & tag in West side 3" Oak 215° 15.66'

Set Nail & tag in South side 2" Poplar 313° 23.14'

Set Nail & tag in West side 3" Oak 347° 11.39'

Set Nail & tag in South side 4" Maple in clump 314° 72.15'

Signed by

Marvin E. Myers

Surveyor's Michigan License No. 31600

Date

