APR 0-7-1998





## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  Crawford	Located In:	Corner Code #		CRAWFORD (	CDUNTÝ:		
in Section 3. Miscellaneous	T_26NR_4W T_25N R_4W TR TR STR STR STR STR	G-13 <sup>2</sup> G-1	19 DEC 97 2:39 P.M.  SANDRA MOURE  RESISTER OF DEEDS  Register of Deeds Stamp & File Number				
4. Lot No, Red	corded Plat	LIBER	3 P	AGE F	2,9 1	6 x	L N
		*	3 4 - 7	89-	1.0	_ 11	_ 1 2
I, <u>Marvin E. Myers</u> , in a field survey on <u>September</u> , 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			5 6—18—7 8—19—9 10—30—	20 21	22	-14 -23 -26	2 4
NOTE: Not more than be recorded on this certific		ime town and range, may	1 31	32 33	34	35	—36 —36

A. Description of original monument and accessories and/or subsequent restoration: CRAWFORD COUNTY G.L.O. Michigan Department of Conservation

G.L.O. April 16, 1839 H. Brevoort D.S. & James H. Mullet D.S.

Mon: Post

Wit: 24" Pine N15°W 38 links 20" Yellow Pine N34°E 93 links Michigan Department of Conservation Billy D. Buckler; October 25, 1956 Corner established from original BT's Mon: 1" pipe with 4" brass cap Wit: 8" Red Oak S34°W 54 ½ links 7" Red Oak N80°E 35 links PEER GROUP APPROVAL

DATE © 7 / 6 . 1997

MELTE OF BYOMEN

Marvin E. Myers, P.S.
County Surveyor

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe and portions of brass cap in clear cut. Replace in exact location with a Standard Crawford County Monument.

Found Red Oak stump \$34°W 36'

Accepted as a perpetuation of the Original Government Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Date \_

Mon – Standard Crawford County Monument.
Set nail and tag in North face 8" Maple N59°W 84.10'
Set nail and tag in North face 8" Poplar N89°W 78.52'
Set nail and tag in North side 10" Black Oak S67°W 78.51'
Set nail and tag in East face 5" Beach in clump S37°E 55.52'
Set Carsonite Post North 1'

*...* 

Signed by

Surveyor's Michigan License No. 31600

MARVIN E.
MYERS
PROFESSIONAL
SURVEYOR
No.
31800